MATERIAL SAFETY DATA SHEET

DATE PRINTED: 11/01/2004 15543700 00000001 3E COMPANY

PAGE

1

SECTION 1. CHEMICAL PRODUCT AND COMPANY INFORMATION

MANUFACTURERS NAME

W.M. BARR & COMPANY, INC.

2105 Channel Avenue Memphis, TN 38113

USA

CARCINOGENICITY

EMERGENCY TELEPHONE #1

901-775-0100

EMERGENCY CONTACT

ADDRESS

W.M. Barr Technical Services

EMERGENCY INFORMATION

"3E" 24 HOUR MEDICAL EMERGENCY #, 800 451-8346. SEE SECTION 5 FOR ADDITIONAL EMERGENCY INFORMATION

INVENTORY ITEM #

ECAS94309

PRODUCT NAME

CS ANTIQUE STRIPPER 18 OZ AERO

REVISED BY W.M. Barr Technical Services **REVISION DATE**

SECTION 2. COMPOSITION/INFORMATION ON INGREDIENTS

CAS# SUBSTANCE DESCRIPTION PERCENT NTP ACGIH OSHA IARC 35- 40 5989-27-5 N N N 60- 65 872-50-4 N N N 20- 25 115-10-6 N N N CITRUS TERPENES N 1-METHYL-2-PYRROLIDONE DIMETHYL ETHER N

SECTION 3. REGULATORY INFORMATION

EXPOSURE LIMITS/REGULATORY INFORMATION

SUBSTANCE DESCRIPTION	REG.AGCY	U/M	TWA	STEL	CEIL	SKIN	PEL
CITRUS TERPENES	ACGIH OSHA	PPM PPM	N/E N/E	N/E N/E	N/E N/E	N N	N/E N/E
1-METHYL-2-PYRROLIDONE	ACGIH OSHA	PPM PPM	N/E N/E	N/E N/E	N/E N/E	N N	N/E N/E
RECOMMENDED EXPOSURE LIMIT:	100 PPM TW	A, As	PROVIDED BY	SUPPLIER.			
DIMETHYL ETHER	ACGIH OSHA	PPM PPM	N/E N/E	N/E N/E	N/E N/E	N N	N/E N/E

ADDITIONAL REGULATORY INFO

The time weighted average (TWA) value described herein is a threshold limit value (TLV) as established by ACGIH. The permissible exposure limit (PEL) is a value established by OSHA.

CALIFORNIA (PROPOSITION #65)
WARNING: Using this product will expose you to chemicals which are known to cause birth defects or other reproductive harm.

SEC. 313 SUPPLIER NOTIFICATION

The following information must be included in all MSDS that are copied and distributed for this material.

This product contains no chemicals subject to the reporting requirements of SARA III: Section 313.

MATERIAL SAFETY DATA SHEET

DATE PRINTED: 11/01/2004 15543700 00000001 3E COMPANY

PAGE

2

SECTION 3. REGULATORY INFORMATION (CONTINUED)

SUBSTANCE DESCRIPTION

PERCENT BY WEIGHT (UPPER LIMIT)

CAS#

1-METHYL-2-PYRROLIDONE

65

872-50-4

CLEAN AIR ACT

This formula contains no known ozone depleting chemicals.

HAZARD COMMUNICATION STANDARD

This document is prepared in accordance with the OSHA Hazard Communication Standard (29 CFR 1910.1200). This MSDS contains thirteen (13) sections.

******************** The following effects and/or symptoms are not expected to be experienced by persons who use this product properly and according to ALL instructions, precautions, and warnings; however, should the product user experience ANY questionable effects or symptoms, the product user should immediately seek medical attention.

SECTION 4. HAZARDS IDENTIFICATION

INHALATION ACUTE EXPOSURE EFFECTS

May cause dizziness; headache; irritation of the respiratory tract and mucous membranes; nausea; giddiness; mental confusion. Intentional misuse of this product by deliberately concentrating and inhaling can be harmful or fatal.

SKIN CONTACT ACUTE EXPOSURE EFFECTS

May cause irritation; itching; burning; redness; inflammation; cracking. May cause dermatitis in people with sensitive skin.

EYE CONTACT ACUTE EXPOSURE EFFECTS

May cause irritation; redness; tearing; burns; conjunctivitis of eyes; stinging of eyes and lids.

INGESTION ACUTE EXPOSURE EFFECTS

Harmful or fatal if swallowed. May cause nausea; vomiting; gastrointestinal irritation; and diarrhea.

CHRONIC EXPOSURE EFFECTS

Reports have associated repeated and prolonged overexposure to solvents with neurological and other physiological damage. Repeated exposure may cause dermatitis. May cause skin irritation; photosensitivity.

MEDICAL CONDITIONS AGGRAVATED

None known.

PRIMARY ROUTE OF EXPOSURE

Inhalation, ingestion, and dermal. _____

SECTION 5. FIRST AID MEASURES

INHALATION

If user experiences breathing difficulty, move to air free of vapors. Administer oxygen or artificial respiration until medical assistance can be rendered.

Wash with soap and water. Get medical attention.

MATERIAL SAFETY DATA SHEET

DATE PRINTED: 11/01/2004 15543700 00000001 3E COMPANY

PAGE

3

SECTION 5. FIRST AID MEASURES (CONTINUED)

EYE CONTACT

Immediately flush with water, remove any contact lens, flush with water for at least 15 minutes. Get medical attention.

INCESTION

DO NOT induce vomiting. Call your poison control center, hospital emergency room, or physician immediately.

NOTE TO PHYSICIAN

This formula is registered with POISINDEX.

Call your local poison control center for further information.

SECTION 6. FIRE FIGHTING MEASURES

HAZARD RATING SOURCE	HMIS	NFPA
HEALTH	2	2
FLAMMABILITY	4	4
REACTIVITY	0	0
OTHER	G	NA

FLASH METHOD FLAME EXTENSION

FLASH POINT

N/E F

N/E C

LOWER EXPLOSION LIMIT

N/E

GENERAL COMMENTS

Aerosol Flammability Classification according to ASTM D-3065-77 and FHSA 1500.45. CPSC FLAMMABILITY: Extremely Flammable Aerosol

EXTINGUISHING METHOD

Use carbon dioxide, dry powder, or foam.

FIRE FIGHTING PROCEDURES

Self-contained respiratory protection should be provided for fire fighters fighting fires in buildings or confined areas. Stay away from heads of containers that have been exposed to intense heat or flame.

FIRE AND EXPLOSION HAZARDS

Contents under pressure. Do not puncture, incinerate or store above 120 degrees F. Exposure to heat or prolonged exposure to sun may cause bursting.

SECTION 7. ACCIDENTAL RELEASE MEASURES

CLEAN-UP

Keep unnecessary people away; isolate hazard area and deny entry. Stay upwind, out of low areas, and ventilate closed spaces before entering. Shut off ignition sources; keep flares, smoking or flames out of hazard area. SMALL SPILLS: take up liquid with sand, earth or other noncombustible absorbent material and place in a plastic container where applicable. LARGE SPILLS: dike far ahead of spill for later disposal.

For transportation related spills contact Chemtrec at 1-800-424-9300 for emergency assistance.

MATERIAL SAFETY DATA SHEET

DATE PRINTED: 11/01/2004 15543700 00000001 3E COMPANY PAGE

4

SECTION 7. ACCIDENTAL RELEASE MEASURES (CONTINUED)

WASTE DISPOSAL

Dispose in accordance with applicable local, state and federal regulations.

SECTION 8. HANDLING AND STORAGE

STORAGE

Replace overcap on container after each use. Store in a cool, dry place. Do not store near flames or at elevated temperatures.

HANDLING

Read carefully all cautions and directions on product label before use. Since empty container retains residue, follow all label warnings even after container is empty. Dispose of empty container according to all regulations. Do not reuse this container.

SECTION 9. TRANSPORT INFORMATION

TRANSPORTATION

For D.O.T. information, contact W.M. Barr Technical Services Department.

SECTION 10. EXPOSURE CONTROLS/PERSONAL PROTECTION

VENTILATION PROTECTION

Use only with adequate ventilation to prevent build-up of vapors. Open all windows and doors. Use only with a cross ventilation of moving fresh air across the work area. If strong odor is noticed or you experience slight dizziness, headache, nausea, or eye-watering - STOP - ventilation is inadequate. Leave area immediately.

RESPIRATORY PROTECTION

For OSHA controlled work place and other regular users - Use only with adequate ventilation under engineered air control systems designed to prevent exceeding appropriate TLV. For occasional use, where engineered air control is not feasible, use properly maintained and properly fitted NIOSH approved respirator for organic solvent vapors. A dust mask does not provide protection against vapors.

SKIN PROTECTION

Wear impermeable gloves. Gloves contaminated with product should be discarded. Promptly remove clothing that becomes soiled with product.

EYE PROTECTION

Safety glasses, chemical goggles or face shields are recommended to safeguard against potential eye contact, irritation, or injury. Contact lenses should not be worn while working with chemicals.

OTHER PROTECTION

Various application methods can dictate use of additional protective safety equipment, such as impermeable aprons, etc., to minimize exposure. A source of clean water should be available in the work area for flushing eyes and skin. Do not eat, drink, or smoke in the work area. Wash hands thoroughly after use. Before reuse, thoroughly clean any clothing or protective equipment that has been contaminated by prior use. Discard any clothing or other protective equipment that cannot be decontaminated, such as gloves or shoes.

KLEAN-STRIP CITRI-STRIP HOUSE BRITE ARMOR ALL KWIK P&D MATERIAL SAFETY DATA SHEET

DATE PRINTED: 11/01/2004 15543700 00000001 3E COMPANY

PAGE

5

SECTION 11. PHYSICAL AND CHEMICAL PROPERTIES

VOLATILE X

BY WEIGHT

BOILING POINT

GT 347.00 F

175.00 C BOILING RANGE: 347 F - 396 F

VAPOR DENSITY (Air = 1.0) HEAVIER THAN AIR

EVAPORATION RATE

SLOWER THAN ETHER

BULK DENSITY

8.029 LBS/GAL AT 75 DEGREES F

ph factor

N/E

PHOTOCHEMICALLY REACTIVE

MAX V.O.C.

96.6% by weight

MAX VAPOR PRESSURE

<1mm Hg at 20 degrees C

SECTION 12. STABILITY AND REACTIVITY

INCOMPATIBILITIES

Incompatible with strong oxidizing agents; reducing agents; halogens; peroxides; vinyl chloride; and iodine chloride.

DECOMPOSITION

Thermal decomposition may produce carbon monoxide; carbon dioxide; oxides of nitrogen; acrid smoke; fumes.

POLYMERIZATION

Will not occur.

STABILITY

SECTION 13. ADDITIONAL INFORMATION

IMPORTANT NOTE

IMPORTANT NOTE
The information contained herein is presented in good faith and believed to be accurate as of the effective date shown above. This information is furnished without warranty of any kind. Employers should use this information only as a supplement to other information gathered by them and must make independent determination of suitability and completeness of information from all sources to assure proper use of these materials and the safety and health of employees. Any use of this data and information must be determined by the user to be in accordance with applicable federal, state and local laws and regulations.

LEGEND:

PPM = parts per million
MG/M3 = milligrams per cubic meter
N/E or NE = none established GT = greater than

KLEAN-STRIP CITRI-STRIP HOUSE BRITE ARMOR ALL KWIK P&D MATERIAL SAFETY DATA SHEET

DATE PRINTED: 11/01/2004 15543700 00000001 3E COMPANY

PAGE

6

SECTION 13. ADDITIONAL INFORMATION
(CONTINUED)

N/A or NA = not applicable TCC = tag closed cup
TCC = tag open cup
PMCC = Pensky-Martens closed cup
IDLH = Immediately Dangerous to Life and Health

END OF MSDS